


To

The Executive Engineer (B)-II,  
Municipal Corporation of Delhi  
Shahdara South Zone (EDMC)  
Delhi



**Subject: - Regarding Structure Stability Safety Certificate of the School,  
Evergreen Public School, Vasundhara Enclave.**

- Ref : - 1. E.E.(B)-II/SH(S)/EDMC/2020/D-343 Dated 24/07/2020.  
2. E.E.(B)-II/SH(S)/EDMC/2020/D-471 Dated 25/08/2020. (Reminder-I)  
3. E.E.(B)-II/SH(S)/EDMC/2020/D-659 Dated 13/10/2020. (Reminder-II)

Dear Sir,

With reference to the MCD/DDA notification/Public Notice (Safety of Building against Earthquakes) dated 06.07.2020, the notice regarding structure stability certificate of my school building .The MCD empanelled structure engineer had inspected the building and after detailed structural safety audit and testing of the existing structure of the building, had issued the **Structure Safety Audit** for the same.

Please find enclosed, herewith, the **structure safety certificate** along with all necessary document for kind perusal of the matter.

Thanking you

Yours faithfully

(Priyanka Gulati)  
Evergreen Public School,  
Vasundhara Enclave, Dallupura, Delhi -110096.

PRINCIPAL  
EVERGREEN PUBLIC SCHOOL  
(RECOGNISED)

# FJ ARCHITECTS & ENGINEERS

## ARCHITECTURE AND INTERIOR WORKS STRUCTURE DRAWINGS

ADDRESS: G-111, GALI NO.-17, OLD MUSTAFABAD, DELHI:-110094.

No. 101/FJA/01

Dated: 04/11/2020

### STRUCTURE STABILITY CERTIFICATE

Property Address : Evergreen Public School,  
Vasundhara Enclave, Dallupura, Delhi – 110096.  
Name of Owner : Jyotirmay Bal Shiksha Samiti  
Plot Area : 5863 Sq.Mtr.  
Type of Building : Educational (RCC Framed Structure)  
No. of Blocks : 01  
Year of Construction : 2006-2008  
No. of Storey : Ground Floor, First Floor, Second and Third Floor.  
Height of building : 14.50 metre

I have inspected the above cited educational building visually on 15/10/2020 at the request of the owner. As per information and details furnished by the owner, the building has been constructed in the year 2006-2008. The existing building consist of Ground floor, First floor, Second Floor & Third Floor with RCC framed structure.

The building having Kota stone & Tile flooring and the walls plastered internal as well as external. The physical condition of the existing building/structure is good. During the inspection I had not found any cracks, buckling and deflections in the columns, beams & slabs and deterioration in the building.

This to certify that the structural part of the building on the above said has been designed on the basis of calculations in accordance with the permissible stresses and slenderness ratio as per National building codes/prevailing BIS codes for structural safety. The above mentioned existing building satisfies the requirements of structural safety from natural hazards including earthquakes/seismic impact.

In view of the above said building is safe and sound at present.

*Principals Seal*  
09/11/2020

PRINCIPAL  
EVERGREEN PUBLIC SCHOOL  
(RECOGNISED)

*A. Zaki*  
Er. ADNAN ZAKI  
Structural Engineer  
Evergreen School  
ADNAN ZAKI  
Signature of Structure Engineer